```
FILE 'REGISTRY' ENTERED AT 07:24:05 ON 11 MAR 2005
                E NITROUS OXIDE/CN
L1
              1 SEA ABB=ON PLU=ON "NITROUS OXIDE"/CN
     FILE 'HCAPLUS' ENTERED AT 07:24:51 ON 11 MAR 2005
L2
          38622 SEA ABB=ON PLU=ON L1 OR N2O OR NITROUS OXIDE OR DINITROGEN
                OXIDE OR DINITROGEN MONOOXIDE
     FILE 'REGISTRY' ENTERED AT 07:24:59 ON 11 MAR 2005
                E RESISTS/CN
     FILE 'HCAPLUS' ENTERED AT 07:25:00 ON 11 MAR 2005
                E RESISTS/CT
                E E3+ALL/CT
L3
          71404 SEA ABB=ON PLU=ON RESISTS/CT OR (MASKING/CT OR MASKS/CT OR
                "ELECTRON BEAM RESISTS"/CT OR "RESISTS (L) ELECTRON-BEAM,
                NEG.-WORKING"/CT OR "RESISTS (L) ELECTRON-BEAM, POS.-WORKING"/C
                T OR "ION BEAM RESISTS"/CT OR PHOTORESISTS/CT OR "NEGATIVE
                PHOTORESISTS"/CT OR "POSITIVE PHOTORESISTS"/CT) OR ("SOLDER
                RESISTS"/CT OR "RESISTS (L) PHOTO-, SOLDER"/CT OR "X-RAY
                RESISTS"/CT) OR "PHOTOMASKS (LITHOGRAPHIC MASKS)"/CT OR
                PHOTORESIST##### OR (MASK#### OR RESIST##) (2A) PHOTO####### OR
                PHOTOMASK#####
                E ORGANOSIL/CT
                E E3+ALL/CT
                E E5+ALL/CT
                S C/ELS AND GLASS
     FILE 'REGISTRY' ENTERED AT 07:27:22 ON 11 MAR 2005
     FILE 'HCAPLUS' ENTERED AT 07:27:27 ON 11 MAR 2005
     FILE 'REGISTRY' ENTERED AT 07:27:53 ON 11 MAR 2005
              1 SEA ABB=ON PLU=ON C/ELS AND SI/ELS AND O/ELS AND GLASS
L4
                D IDE
L5
              4 SEA ABB=ON PLU=ON C/ELS AND GLASS
         622635 SEA ABB=ON PLU=ON C/ELS AND O/ELS AND SI/ELS
L6
           3892 SEA ABB=ON PLU=ON SILICATE AND L6
T.7
     FILE 'HCAPLUS' ENTERED AT 07:29:46 ON 11 MAR 2005
           2121 SEA ABB=ON PLU=ON L7(L)(GLASS OR OSG)
L8
            182 SEA ABB=ON PLU=ON OSG OR ORGANOSILICAT####(4A)GLASS###
L9
            120 SEA ABB=ON PLU=ON OSG OR ORGANIC SILICAT####(4A)GLASS###
L10
             16 SEA ABB=ON PLU=ON L7(L)SOG
L11
            122 SEA ABB=ON PLU=ON L7(L) (SPUN OR SPUNON OR SPINON OR SPIN)
L12
L13
          90241 SEA ABB=ON PLU=ON ((L4 OR L5) OR L7)
          63201 SEA ABB=ON PLU=ON (L4 OR L5) OR (L8 OR L9 OR L10 OR L11 OR
L14
                L12)
                E GLASSES/CT
                E GLASS/CT
           1043 SEA ABB=ON PLU=ON GLASS(L)(ORGANOSILIC###### OR ORGANIC
L15
                SILICA#### OR ORGANOSILICA####)
L16
          64054 SEA ABB=ON PLU=ON (L8 OR L9 OR L10 OR L11 OR L12) OR L15 OR
                (L4 OR L5)
L17
           3270 SEA ABB=ON PLU=ON (L8 OR L9 OR L10 OR L11 OR L12) OR L15 OR
                L4
             77 SEA ABB=ON PLU=ON L3 AND L17
T.18
L19
              3 SEA ABB=ON PLU=ON L2 AND L18
                D ALL HITSTR TOT
L20
             27 SEA ABB=ON PLU=ON L2 AND L3 AND (L8 OR L9 OR L10 OR L11 OR
                L12 OR L13 OR L14 OR L15 OR L16 OR L17 OR L18)
             24 SEA ABB=ON PLU=ON L20 NOT L19
L21
T.22
             10 SEA ABB=ON PLU=ON L21 AND (STRIP###### OR REMOV##### OR
                ETCH###### OR ATTACK#### OR DECOMPOS##### OR SACRIFIC#####) (4A)
                (PHOTORESIST##### OR RESIST)
                D BIB AB HITSTR TOT
                D L22 ALL HITSTR TOT
```

1 SEA ABB=ON PLU=ON (L9 OR L10 OR L11 OR L12) AND L2 AND L3

L23

•			10,000,000
3		•	
			D ALL HITSTR
L24		2121	SEA ABB=ON PLU=ON L7(L)GLASS
L25			SEA ABB=ON PLU=ON L24 AND L2 AND L3
			SEA ABB=ON PLU=ON L25 NOT L23
L26		2	
			D ALL HITSTR TOT
			E RESISTS/CT
			E E3+ALL/CT
L27		5422	SEA ABB=ON PLU=ON (RESISTS/CT OR MASKING/CT OR MASKS/CT OR
12,		V 122	· · · · · · · · · · · · · · · · · · ·
			"ELECTRON BEAM RESISTS"/CT OR "RESISTS (L) ELECTRON-BEAM,
			NEGWORKING"/CT OR "RESISTS (L) ELECTRON-BEAM, POSWORKING"/C
			T OR "ION BEAM RESISTS"/CT OR PHOTORESISTS/CT OR "NEGATIVE
			PHOTORESISTS"/CT OR "POSITIVE PHOTORESISTS"/CT OR "RESISTS (L)
			PHOTO-, UV, POSWORKING"/CT OR "RESISTS (L) PHOTO-, UV"/CT OR
			"RESISTS (L) PHOTO-, DRY-FILM"/CT OR "RESISTS (L) PHOTO-,
			NEGWORKING"/CT OR "RESISTS (L) PHOTO-, POSWORKING"/CT OR
			"RESISTS (L) PHOTO-, SOLDER"/CT OR "SOLDER RESISTS"/CT OR
			"RESISTS (L) PHOTO-, SOLDER"/CT OR "X-RAY RESISTS"/CT)(L) (REMOV
			###### OR SACRIFIC###### OR ETCH###### OR STRIP OR STRIPP####)
T.28		43	SEA ABB=ON PLU=ON L2 AND L27
L29			SEA ABB=ON PLU=ON (OSG OR GLASS OR ORGANOSILIC####### OR
БС Э		7	
			ORGANO SILIC##### OR ORGANIC SILIC####) AND L28
			D ALL HITSTR TOT
L30		. 265	SEA ABB=ON PLU=ON (L11 OR L12) OR (L18 OR L19 OR L20 OR L21
			OR L22 OR L23) OR (L25 OR L26) OR (L28 OR L29)
L31			SEL PLU=ON L30 1- PRN : 226 TERMS
	DTT D	IMDIV	, JAPIO' ENTERED AT 07:44:56 ON 11 MAR 2005
	LILE		
L32			SEA ABB=ON PLU=ON L31
L33		33	SEA ABB=ON PLU=ON L32 AND (STRIP##### OR REMOV##### OR
			SACRIFIC#######) (3A) (RESIST OR PHOTORESIST)
L34		13	SEA ABB=ON PLU=ON L33 AND (NITROUS OR N2O OR DINITROGEN
			OXIDE OR DINITROGEN MONOOXIDE)
			D MAX 1-13
T 2 E		1	SEA ABB=ON PLU=ON L34 AND (OSG OR GLASS#### OR ORGANOSIL#####
L35		4	
			## OR SOG)
			D MAX 1-4
	FILE		I-EPLUS' ENTERED AT 07:48:38 ON 11 MAR 2005
L36		154	SEA ABB=ON PLU=ON (STRIP##### OR REMOV##### OR SACRIFIC######
			#) (3A) (RESIST OR PHOTORESIST)
L37		15	SEA ABB=ON PLU=ON L36 AND (OSG OR GLASS#### OR ORGANOSIL#####
יכת		13	
		_	## OR SOG)
L38		1	SEA ABB=ON PLU=ON L36 AND (NITROUS OR N2O OR DINITROGEN
			OXIDE OR DINITROGEN MONOOXIDE)
L39		0	SEA ABB=ON PLU=ON L37 AND L38
			D L38 ALL
	שוום	י ער א סי	LUS' ENTERED AT 07:49:48 ON 11 MAR 2005
T 40	LIDE		
L40			SEA ABB=ON PLU=ON ASH####(3A) (RESIST OR PHOTORESIST)
L41		235	SEA ABB=ON PLU=ON' ((L7 OR L8 OR L9 OR L10 OR L11 OR L12) OR
			L15 OR (L17 OR L18 OR L19 OR L20 OR L21 OR L22 OR L23 OR L24
		-	OR L25 OR L26 OR L27 OR L28 OR L29 OR L30)) AND L40
L42		1	SEA ABB=ON PLU=ON L41 AND (L1 OR NITROUS OR N2O OR DINITROGEN
			OXIDE OR DINITROGEN MONOOXIDE)
			D ALL HITSTR
			D VIII III III
	m.r	100=-	ENDOUG ENTERDED AT 07.50.05 ON 11 MAR 2005
	LILE	SCIS	EARCH' ENTERED AT 07:52:05 ON 11 MAR 2005
			E OLNESS G, 1990/RE
L43		1	SEA ABB=ON PLU=ON "OLNESS G, 1993, V315, P261, P MRS S"/RE
			D ALL